

HEALTH SAFETY & ENVIRONMENTAL INFORMATION

During Painting

Always Work in a well-ventilated area. Wear appropriate attire, especially gloves and eye-protection gear. Avoid contact with skin as it may cause irritation.

Cleaning

Wash all the tools with water immediately after application.

Safety instructions

In case of eye contact, rinse immediately with water and seek immediate medical treatment. To remove paint your skin, use soap and water or appropriate cleanser. In the event of spillage, contain and collect spilt paint using sand or earth.

Precautions

Avoid painting when the temperature is below 10°C. Painting is not recommended if the moisture content and alkalinity of the walls are high. Moisture content of the wall should be below 16 % (measured by protimeter) and alkalinity of the wall should be below P^H 9. Relative humidity should be below 85 %. Painting on a newly-plastered wall is recommended after 12 weeks of curing.

Storage

Store paint in a cool, dry and well-ventilated place away from heat sources, flammables or direct sunlight. Keep container tightly closed secure, upright position. Do not store near food, drinks or animal feed. Keep out of reach of children. Do not dispose unwanted paint into drains, water sources or sewers. To dispose safely pour unwanted paint onto old newspaper and let it dry before placing it in a proper receptacle.

Environment

Does not contain any added lead, mercury or chromium compounds.